



VOLVO XC60: 1LAH870

Vinnumber:	VV1DZARC1G2809609	Versionname:	2.0 D3 2WD KINETIC
First Registrationdate:	31/07/2015	Fiscalpower:	
Expertise Mileage:	80581	Power Kw:	110
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4510
Maintenance:	OVER 13471 KM		
Maintenance:	3/08/2020		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar removable
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/65/17/108 V LightMetal				
Summer tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			0,00
Door RL, Scratch(es), Acceptable			0,00



Door RR, Repaired, P - Check 0,00



Bumper F, Repaired, Acceptable 0,00



Wing RR, Repaired, Acceptable 0,00



Door FR, Repaired, P - Check 0,00



Roof pillar R, Repaired, Acceptable 0,00



Wing RL, Scratch(es), Acceptable 0,00



Wing FR, Repaired, Acceptable 0,00



Hood, Dent(s) and scratch(es), Acceptable 0,00

Bumper, Dent(s) and scratches, Acceptable

0,00



Electrical circuit, Not functioning (well), P - Check

0,00



Interior, Worn, Acceptable

0,00



Bumper R, Dent(s), Acceptable

0,00

