



BMW 2 GRAN TOURER: 1TTY813

Vinnnumber:	WBA2E510705H14877	Versionname:	218d (100kW)
First Registrationdate:	13/02/2018	Fiscalpower:	
Expertise Mileage:	98180	Power Kw:	100
Bodytype:		Body colour:	Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2103
Fueltype:	Diesel		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting:	Headlighting Halogen	Rear parking sensors	
Type of GPS:	GPS big screen color	Type of Tow bar	Tow bar removable
Type of Lining:	Lining artificial leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

	205/60/16/92 H			
Summer tyres:	Fr.L.	Semperit: 5 mm	Fr.R.	Semperit: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5
Tyre profile depth FR				5
Tyre profile depth RL				5
Tyre profile depth RR				5
Tyre size FL				205/60 R 16 92 H
Tyre type FL				Summer
Tyre make FL				2477
Tyre make RL				261

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3648,15
--------------------------	----------------

Alloy rim RR, Scratch(es), Repair and paint (complete)	114,00
---	---------------



Wing RL, Scratch(es), Repair and paint (complete)	369,84
--	---------------



Alloy rim FL, Scratch(es), Acceptable

0,00



Door FR, Scratch(es), Repair and paint (complete)

382,02



Door RR, Scratch(es), Repair and paint (complete)

382,02



Bumper R, Scratch(es), Repair and paint (complete)

254,16



Door RL, Dent(s), Acceptable

0,00



Wing FL, Scratch(es), Acceptable

0,00



Windscreen, Scratch(es), Replace

548,92



Rear window, Scratch(es), Replace

445,00



Step R, Scratch(es), Repair and paint (complete)

138,67



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)

398,84



Step L, Scratch(es), Repair and paint (complete)

138,67



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)

362,01



Alloy rim RL, Scratch(es), Repair and paint (complete)

114,00

