



BMW X3: 1UUM529			
Vinnumber:	WBATR51030LF95455	Versionname:	xDrive20i (135 kW)
First Registrationdate:	30/07/2018	Fiscalpower:	
Expertise Mileage:	98369	Power Kw:	135
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1115
Fueltype:	Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options			
Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	Tow bar collapsible
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining artificial leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

225/60/18/104 W				
Summer tyres:	Fr.L.	Yokohama: 4 mm	Fr.R.	Yokohama: 4 mm
	Re.L.	Yokohama: 4 mm	Re.R.	Yokohama: 4 mm
Tyre profile depth FL:				4
Tyre profile depth FR:				4
Tyre profile depth RL:				4
Tyre profile depth RR:				4
Tyre size FL:				225/60 R 18 104 W
Tyre type FL:				Summer
Tyre make FL:				2481
Tyre make RL:				2481

Assistance equipment			
Emergency spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	1429,93
Bumper moulding F, Scratch(es), Smart repair	121,70




Bumper F, Scratch(es), Spot repair	127,12
---	---------------




Bonnet, Scratch(es), Repair and paint (complete)

417,70



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)

304,99



Wing RR, Dent(s) and scratch(es), Acceptable

0,00



Door RL, Dent(s) and scratch(es), Repair and paint (complete)

458,42



Outside rear-view mirror housing L, Scratch(es), Acceptable

0,00



Tailgate / Boot, Scratch(es), Acceptable

0,00

