



BMW X2: DP8934

Vinnumber:	WBAYK910X05N20013	Versionname:	sDrive20d 140kW Aut.
First Registrationdate:	4/06/2019	Fiscalpower:	
Expertise Mileage:	94048	Power Kw:	140
Bodytype:		Body colour:	Orange
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2815
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-Alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Degree of wear

	225/59/18/99 W			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm
Tyre profile depth FL				4
Tyre profile depth FR				4
Tyre profile depth RL				4
Tyre profile depth RR				4
Tyre size FL				225/59 R 18 99 W
Tyre type FL				Summer
Tyre make FL				264
Tyre make RL				264

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT 520,46

Rear light L, Crack, Replace 137,00



Alloy rim FR polished, Scratch(es), Acceptable 0,00



Wing trim RR, Scratch(es), Acceptable

0,00



Boot cover, Broken, Replace

60,00



Bumper R, Scratch(es), Repair and paint (complete)

254,16



Door RR, Dent(s), Paintless dent repair

69,30



Rear window, Scratch(es), Acceptable

0,00

