



**OPEL ASTRA SPORTS TOURER: 1XE843**

Vinnumber:	<b>WOLBF8EG2G8090371</b>	Versionname:	<b>1.6 CDTI 100KW S/S DYNAMIC</b>
First Registrationdate:	<b>5/07/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>191325</b>	Power Kw:	<b>100</b>
Bodytype:		Body colour:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>1106</b>
Fueltype:	<b>Diesel</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

**Options**

Number of keys total:	<b>2</b>	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	<b>No Tow bar</b>
Radio multimedia:			
Type of headlighting:	<b>Headlighting Halogen</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining artificial leather</b>		
Type of climate control:	<b>Autom climate control</b>		

**Limited Technical Inspection**

**Degree of wear**

	<b>205/55/16/91 V</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Uniroyal: 4 mm</b>	Re.R.	<b>Uniroyal: 4 mm</b>
Tyre profile depth FL				<b>4</b>
Tyre profile depth FR				<b>4</b>
Tyre profile depth RL				<b>4</b>
Tyre profile depth RR				<b>4</b>
Tyre size FL				<b>205/55 R 16 91 V</b>
Tyre make FL				<b>261</b>
Tyre make RL				<b>265</b>

**Assistance equipment**

Emergency spare wheel:	<b>Yes</b>	Jack:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

Total cost ex VAT:	<b>699,42</b>
Wing RL, Dent(s), Acceptable:	<b>0,00</b>



Seat cover FL, Worn, Acceptable:	<b>0,00</b>
----------------------------------	-------------



Engine, Not functioning (well), Check 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00



Interior, Worn, Acceptable 0,00



Wing FR, Dent(s), Paintless dent repair 69,30



Backrest cover FL, Worn, Acceptable 0,00



Wing FR, Scratch(es), Acceptable 0,00



Outer sill R, Dent(s) and scratch(es), Spot repair 185,12



Roof, Chemical polution, Acceptable 0,00



Rear window, Scratch(es), Replace 445,00



Bumper R, Scratch(es), Acceptable 0,00

