



**MAZDA 3 HATCHBACK: 1UKQ688**

Vinnumber:	<b>3MZBN64S60M340800</b>	Versionname:	<b>1.5 Skyactiv-D 77kW Plug Edition</b>
First Registrationdate:	<b>31/05/2018</b>	Fiscalpower:	
Expertise Mileage:	<b>76970</b>	Power Kw:	<b>77</b>
Bodytype:		Body colour:	<b>Red</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>2606</b>
Fueltype:	<b>Diesel</b>		
Maintenance:	<b>OK</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Number of keys total:	<b>2</b>	Luggage cover:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:		Type of Tow bar:	<b>No Tow bar</b>
Seats F heated:			
Type of headlighting:	<b>Headlighting Halogen</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining semi-artificial leather</b>		
Type of climate control:	<b>Autom climate control</b>		

**Limited Technical Inspection**

**Degree of wear**

<b>205/60/16/92 MS</b>			
Winter tyres:	Fr.L. <b>Michelin: 5 mm</b>	Fr.R. <b>Michelin: 5 mm</b>	
	Re.L. <b>Michelin: 5 mm</b>	Re.R. <b>Michelin: 5 mm</b>	
Tyre profile depth FL:			<b>5</b>
Tyre profile depth FR:			<b>5</b>
Tyre profile depth RL:			<b>5</b>
Tyre profile depth RR:			<b>5</b>
Tyre size FL:			<b>205/60 R 16 92 MS</b>
Tyre type FL:			<b>Winter</b>
Tyre make FL:			<b>261</b>
Tyre make RL:			<b>261</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

Total cost ex VAT 1267,43

Wing RL, Dent(s) and scratch(es), Repair and paint (complete) 0,00



Step L, Scratch(es), Acceptable 0,00



Door FL, Scratch(es), Repair and paint (complete)

0,00



Windscreen, Crack, Replace

0,00



Door RL, Scratch(es), Repair and paint (complete)

411,02



Bonnet, Chemical polution, Repair and paint (complete)

348,09



Bumper R, Scratch(es), Repair and paint (complete)

254,16



Bumper F, Scratch(es), Repair and paint (complete)

254,16

