



VOLKSWAGEN CADDY MAXI: 1TBT617

Vinnumber:	WV2ZZZ2KZJX017491	Versionname:	2.0 CRTDi 75kW SCR BMT Maxi Dark & Cool
First Registrationdate:	18/09/2017	Fiscalpower:	
Expertise Mileage:	187206	Power Kw:	75
Bodytype:		Body colour:	Black
Gearbox:	MAN 5 VIT	Type of rims (mounted):	Steel
Transmission:		Parking lot:	2607
Fueltype:	Diesel		
Maintenance:	NOT OK		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Rear parking sensors:	
Cruise Control:		Type of Tow bar:	No Tow bar
Steering wheel multifunctional:			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

205/55/16/92 H			
Summer tyres:	Fr.L.	Fr.R.	Michelin: 5 mm
	Re.L.	Re.R.	Michelin: 5 mm
Tyre profile depth FL			5
Tyre profile depth FR			5
Tyre profile depth RL			5
Tyre profile depth RR			5
Tyre size FL			205/55 R 16 92 H
Tyre type FL			Summer
Tyre make FL			261
Tyre make RL			261

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	2101,65
Windscreen, Scratch(es), Replace	0,00



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)	434,42
--	---------------



Seat cover R, Stain, Cleaning 25,00



Wheel cover FR, Scratch(es), Acceptable 0,00



Service, Maintenance, Check 0,00

No pictures to display

Wheel cover RR, Scratch(es), Replace 27,00



Boot cover, Missing, Replace 45,00



Outside rear-view mirror base L, Scratch(es), Smart repair 132,76



Bodywork, Not original part, Remove lettering 0,00

No pictures to display

Wing FL, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Repair and paint (complete) 248,62



Roof liner, Damaged, Replace 489,00





Outside rear-view mirror housing L, Scratch(es), Acceptable

0,00



Door FL, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), Repair and paint (complete)

190,62



Door RL, Scratch(es), Acceptable

0,00



Bodywork, Missing, Replace

34,28



Steering wheel, Worn, Acceptable

0,00



Outside rear-view mirror base R, Scratch(es), Smart repair

132,76



Outer sill R, Scratch(es), Repair and paint (complete)

279,45



Outside rear-view mirror housing R, Scratch(es), Acceptable

0,00



Boot lid covering R, Scratch(es), Replace

35,74



Wheel cover FL, Missing, Replace

27,00

