



VOLVO V90: 1SHR080

Vinnumber:	YV1PWA8BDJ1036673	Versionname:	D4 Geartronic Inscription
First Registrationdate:	16/05/2017	Fiscalpower:	
Expertise Mileage:	115157	Power Kw:	140
Bodytype:		Body colour:	Brown
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3407
Fueltype:	Diesel		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Sun Roof electric:	
Seats F heated:		Panoramic roof:	
Radio multimedia:		Luggage cover:	
Type of headlighting:	Headlighting LED	Front parking sensors:	
Type of GPS:	GPS big screen color	Rear parking sensors:	
Type of Lining:	Lining artificial leather	Type of Tow bar:	Tow bar collapsible
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

245/45/18/92 H			
Summer tyres:	Fr.L. Michelin: 5 mm	Fr.R. Michelin: 5 mm	
	Re.L. Michelin: 5 mm	Re.R. Michelin: 5 mm	
Tyre profile depth FL:			5
Tyre profile depth FR:			5
Tyre profile depth RL:			5
Tyre profile depth RR:			5
Tyre size FL:			245/45 R 18 92 H
Tyre type FL:			Summer
Tyre make FL:			261
Tyre make RL:			261

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT 700,00

Rear window, Scratch(es), Replace 0,00



Bumper F, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Wing RL, Scratch(es), Acceptable 0,00



Alloy rim RR polished, Scratch(es), Repair and paint (complete) 175,00



Alloy rim RL polished, Scratch(es), Repair and paint (complete) 175,00



Rear light L, Scratch(es), Acceptable 0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 175,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 175,00

