



**VOLKSWAGEN CRAFTER: 1SPG819**

Vinnumber:	<b>WV1ZZZSYZH9014059</b>	Versionname:	<b>35 2.0TDI 103/140 L3H3</b>
First Registrationdate:	<b>20/06/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>175200</b>	Power Kw:	<b>103</b>
Bodytype:		Body colour:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Steel</b>
Transmission:		Parking lot:	<b>lcv28</b>
Fueltype:	<b>Diesel</b>		
Maintenance:	<b>OK</b>		
Type of rims (mounted):	<b>Steel</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Light Commercial Vehicle</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Number of keys total:	<b>2</b>	Front parking sensors:	
Cruise Control:		Rear parking sensors:	
Type of headlighting:	<b>Headlighting Halogen</b>	Type of Tow bar:	<b>No Tow bar</b>
Type of GPS:	<b>No GPS</b>		
Type of Lining:	<b>Lining artificial leather</b>		
Type of climate control:	<b>Manual climate control</b>		

**Limited Technical Inspection**

**Degree of wear**

<b>205/75/16/91 MS</b>				
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>
Tyre profile depth FL:				<b>5</b>
Tyre profile depth FR:				<b>5</b>
Tyre profile depth RL:				<b>5</b>
Tyre profile depth RR:				<b>5</b>
Tyre size FL:				<b>205/75 R 16 91 MS</b>
Tyre type FL:				<b>Winter</b>
Tyre make FL:				<b>261</b>
Tyre make RL:				<b>261</b>

**Assistance equipment**

Spare wheel:	<b>Yes</b>	Jack:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

<b>Total cost ex VAT</b>	<b>644,92</b>
--------------------------	---------------

<b>Roof pillar L, Scratch(es), Repair and paint (complete)</b>	<b>198,16</b>
--	---------------



<b>Reflector, Crack, Replace</b>	<b>50,88</b>
----------------------------------	--------------



Bumper R, Crack, Replace

395,88



Bodywork, Not original part, Remove lettering

0,00

*No pictures to display*