



VOLKSWAGEN TOURAN: 1URA084

Vinnumber:	WVGZZZ1TZJW116846	Versionname:	1.6 TDi SCR 85kW DSG Highline
First Registrationdate:	13/07/2018	Fiscalpower:	
Expertise Mileage:	65826	Power Kw:	85
Bodytype:	MPV	Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Front	Parking lot:	1208
Fueltype:	Diesel		
Maintenance:	OK		
Maintenance:	over 204 dagen		
Maintenance:	24800		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Sun Roof electric:	
Steering wheel multifunctional:		Panoramic roof:	
Seats F heated:		Luggage cover:	
Radio multimedia:		Front parking sensors:	
Type of headlighting:	Headlighting Halogen	Rear parking sensors:	
Type of GPS:	GPS big screen color	Type of Tow bar:	No Tow bar
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		
Type of GPS storage:	SD present		

Limited Technical Inspection

Degree of wear

205/60/16/96 V			
Summer tyres:	Fr.L. Pirelli: 5 mm	Fr.R. Pirelli: 5 mm	
	Re.L. Pirelli: 5 mm	Re.R. Pirelli: 5 mm	
Tyre profile depth FL			5
Tyre profile depth FR			5
Tyre profile depth RL			5
Tyre profile depth RR			5
Tyre size FL			205/60 R 16 96 V
Tyre type FL			Summer
Tyre make FL			264
Tyre make RL			264

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT 731,29

Bumper F, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Repair and paint (complete) 254,16



Bumper trim R, Scratch(es), Smart repair 121,70



Wing FR, Scratch(es), Repair and paint (complete) 264,21



Bonnet, Scratch(es), Polish 0,00



Headlight R, Scratch(es), Polish 0,00





Roof liner, Stain, Cleaning

25,00



Outside rear-view mirror housing R, Scratch(es), Polish

66,22

