



BMW 2 GRAN TOURER: 1TSQ163

Vinnumber:	WBA2E310405K04570	Versionname:	216d (85kW)
First Registrationdate:	31/01/2018	Fiscalpower:	
Expertise Mileage:	93760	Power Kw:	85
Bodytype:		Body colour:	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2105
Fueltype:	Diesel		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Steering wheel multifunctional:		Front parking sensors:	
Type of headlighting:	Headlighting Halogen	Rear parking sensors:	
Type of GPS:	GPS big screen color	Type of Tow bar:	No Tow bar
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		

Limited Technical Inspection

Degree of wear

205/60/16/92 H				
Summer tyres:	Fr.L.	Kleber: 5 mm	Fr.R.	Kleber: 5 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm
Tyre profile depth FL				5
Tyre profile depth FR				5
Tyre profile depth RL				5
Tyre profile depth RR				5
Tyre size FL				205/60 R 16 92 H
Tyre type FL				Summer
Tyre make FL				2479
Tyre make RL				2479

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT 1047,25

Bonnet, Dent(s) and scratch(es), Repair and paint (complete) 348,09



Door FR, Dent(s), Acceptable 0,00



Step R, Scratch(es), Acceptable

0,00



Rear window, Scratch(es), Replace

445,00



Bumper R, Scratch(es), Repair and paint (complete)

254,16

