



TOYOTA C-HR: 1XVE996

Vinnumber:	NMTK33BX20R039468	Versionname:	1.8 VVT i-Hybrid C-Hic E-CVT
First Registrationdate:	4/06/2020	Fiscalpower:	
Expertise Mileage:	20523	Power Kw:	90
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2824
Fueltype:	Hybrid Petrol		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining semi-artificial leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

225/50/18/92 H			
Summer tyres:	Fr.L. Michelin: 5 mm	Fr.R. Michelin: 5 mm	
	Re.L. Michelin: 5 mm	Re.R. Michelin: 5 mm	
Tyre profile depth FL:			5
Tyre profile depth FR:			5
Tyre profile depth RL:			5
Tyre profile depth RR:			5
Tyre size FL:			225/50 R 18 92 H
Tyre type FL:			Summer
Tyre make FL:			261
Tyre make RL:			261

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT 1635,29

Bumper R, Scratch(es), Repair and paint (complete) 254,16



Wing trim FR, Scratch(es), Replace 46,28



Door FL, Dent(s), Acceptable

0,00



Step R, Scratch(es), Acceptable

0,00



Roof, Chemical polution, Polish

0,00



Bumper F, Scratch(es), Repair and paint (complete)

283,16



Bumper trim R, Scratch(es), Replace

250,37



Wing trim RR, Scratch(es), Replace

101,00



Bonnet, Scratch(es), Acceptable

0,00



Door panel RR, Scratch(es), Smart repair

121,70



Alloy rim FL polished, Scratch(es), Repair and paint (complete)

175,00



Roof pillar L, Scratch(es), Acceptable

0,00



Outside rear-view mirror glass L, Broken, Replace

21,60



Door RR, Scratch(es), Repair and paint (complete)

382,02

