



**RENAULT ESPACE: 1TWN947**

|                                   |                          |                        |                           |
|-----------------------------------|--------------------------|------------------------|---------------------------|
| Vinnumber:                        | <b>VF1RFC00860105058</b> | Versionname:           | <b>Energy dCi 130 Zen</b> |
| First Registrationdate:           | <b>6/03/2018</b>         | Fiscalpower:           |                           |
| Expertise Mileage:                | <b>200524</b>            | Power Kw:              | <b>96</b>                 |
| Bodytype:                         |                          | Body colour            | <b>Silver</b>             |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Type of rims (mounted) | <b>Aluminium</b>          |
| Transmission:                     |                          | Parking lot            | <b>2810</b>               |
| Fueltype:                         | <b>Diesel</b>            |                        |                           |
| Maintenance                       | <b>OK</b>                |                        |                           |
| Type of rims (mounted)            | <b>Aluminium</b>         |                        |                           |
| Certificate of Conformity         | <b>Yes</b>               |                        |                           |
| Category                          | <b>Passenger Car</b>     |                        |                           |
| Registration Certificate Car (BE) | <b>Yes</b>               |                        |                           |

**Options**

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Number of keys total           | <b>2</b>                     | Panoramic roof        |                   |
| Cruise Control                 |                              | Luggage cover         |                   |
| Steering wheel multifunctional |                              | Front parking sensors |                   |
| Type of headlighting           | <b>Headlighting LED</b>      | Rear parking sensors  |                   |
| Type of GPS                    | <b>GPS big screen color</b>  | Type of Tow bar       | <b>No Tow bar</b> |
| Type of Lining                 | <b>Lining fabrics</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |

**Limited Technical Inspection**

**Degree of wear**

|                       |       |                |       |                  |
|-----------------------|-------|----------------|-------|------------------|
| 235/65/17/92 H        |       |                |       |                  |
| Summer tyres:         | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm   |
|                       | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm   |
| Tyre profile depth FL |       |                |       | 5.0              |
| Tyre profile depth FR |       |                |       | 5.0              |
| Tyre profile depth RL |       |                |       | 5.0              |
| Tyre profile depth RR |       |                |       | 5.0              |
| Tyre size FL          |       |                |       | 235/65 R 17 92 H |
| Tyre type FL          |       |                |       | Summer           |
| Tyre make FL          |       |                |       | 261              |
| Tyre make RL          |       |                |       | 261              |

**Assistance equipment**

|                                          |            |      |            |
|------------------------------------------|------------|------|------------|
| Emergency spare wheel                    | <b>Yes</b> | Jack | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |      |            |
| Number of charging cables (rapid charge) | <b>0</b>   |      |            |

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>553,81</b> |
|-------------------|---------------|

|                                    |             |
|------------------------------------|-------------|
| Door RL, Chemical polution, Polish | <b>0,00</b> |
|------------------------------------|-------------|



|                                   |             |
|-----------------------------------|-------------|
| Bumper R, Scratch(es), Acceptable | <b>0,00</b> |
|-----------------------------------|-------------|



Bumper trim R, Scratch(es), Smart repair

121,70



Wing RL, Scratch(es), Acceptable

0,00



Door RL, Dent(s), Acceptable

0,00



Bumper F, Scratch(es), Repair and paint (complete)

304,99



Bumper moulding R, Scratch(es), Spot repair

127,12



Door RR, Scratch(es), Acceptable

0,00



Bumper spoiler F, Scratch(es), Acceptable

0,00



Brand badge R, Deformed / Strained, Acceptable

0,00



Wing FR, Scratch(es), Acceptable

0,00



Door trim RR, Bad repair, Check

0,00



Tailgate / Boot, Scratch(es), Acceptable

0,00



Wing RR, Dent(s), Acceptable

0,00



Rear window, Scratch(es), Acceptable

0,00



Bonnet, Scratch(es), Acceptable

0,00

