



Renault Clio: 1UHV356			
Vinnumber:	VF15R240A60600244	Versionname:	
First Registrationdate:	16/05/2018	Fiscalpower:	
Expertise Mileage:	86672	Power Kw:	66
Bodytype:		Body colour	Silver
Gearbox:	MAN 5 VIT	Type of rims (mounted)	Steel
Transmission:		Parking lot	1727
Fueltype:	Petrol		
Maintenance	OK		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options			
Number of keys total	2	Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Degree of wear

185/65/15/91 H				
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				185/65 R 15 91 H
Tyre type FL				Winter
Tyre make FL				261
Tyre make RL				261

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2277,66
Wheel cover RL, Scratch(es), Replace	28,80



Wing FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Door FR, Scratch(es), Acceptable

0,00



Wing RR, Scratch(es), Repair and paint (complete)

295,87



Wheel cover FR, Scratch(es), Replace

28,80



Bumper R, Scratch(es), Repair and paint (complete)

203,32



Rear window, Scratch(es), Replace

385,00



Bumper F, Scratch(es), Repair and paint (complete)

203,32



Door RR, Scratch(es), Acceptable

0,00



Wheel cover RR, Scratch(es), Replace

28,80



Wheel cover FL, Missing, Replace

28,80



Step L, Dent(s) and scratch(es), Repair and paint (complete)

138,67



Windscreen, Scratch(es), Replace

468,14



Windscreen, Stone chip(s), Replace

468,14

