Rapport

Oct.Combi TSI 130 CNG Sty.Aut.
KXN81L

Informations sur le véhicule

Lieu de stockage	SE-41-GOTEBORG-BCA
VIN	TMBJH9NE7K0188816
Immatriculation	KXN81L
Catégorie de véhicule	
Marque	Skoda
Modèle	Octavia Combi (5E5)(03.2017->)
Energie	Petrol
Puissance	96.0 DIN
Boîte de vitesses	Automatic
Nombre de vitesses	11
4 roues motrices	false
Nombre de portes	5
Nombre de places	5
Couleur Fabricant	
Couleur de la Peinture	Black
Mise en circulation	2019-05-13
Kilométrage dernière opération maintenance	192069 km
Dernier kilométrage	2022-08-30
Texte libre Warning	Other Time for service. Warninglamp for tyres.

Photos

Oct.Combi TSI 130 CNG Sty.Aut.
KXN81L

✚ Options

Carrosserie **Estate**

Equipements et options

Outside

Metallic paint	✔
Xenon headlamps	✖
Sun roof	✖
Panoramic roof	✖
Led front and rear lamps	✔
Led Rearlamp	✔
Tow-bar	✖

Parking

Front parking aid	✔
Rear parking aid	✔
Reverse camera	✔
Park assistant	✖

Dashboard

Cruise control	✖
Adaptative cruise control	✔
Navigation system	✔
Manual air-conditionning	✖
Automatic air-conditionning	✔
Head-up display	✖

Seats

Leather upholstery	✖
Partially leather upholestry	✖
Leather/Alcantara upholstery	✖
Electrically adjustable seats	✖
Memory driver seat	✖
Heated seats	✔

Others

Electric boot/hatchback	✔

! Dommages

Position	Rear-right door
Réparation	Repair with paint
Nature du dommage	Dent

Position	Front-right door
Réparation	Repair with paint
Nature du dommage	Dent

Position	Left-side underbody
Réparation	Paint
Nature du dommage	Scratch

Position	Front bumper
Réparation	Paint
Nature du dommage	Paint damaged

Position	Roof
Réparation	Repair with paint
Nature du dommage	Dents

Position	Bonnet
Réparation	Repair with paint
Nature du dommage	Dents

Position	Front-right wing
Réparation	Repair with paint
Nature du dommage	Dent

Position	Front -left light
Réparation	Replacement
Nature du dommage	Cracked

Position	Front -left wing
Réparation	Paint
Nature du dommage	Paint damaged

Position	Front -left door
Réparation	Repair with paint
Nature du dommage	Dents

Position	Rear-left wing
Réparation	Repair with paint
Nature du dommage	Dents

Position	Rear bumper
Réparation	Repair with paint
Nature du dommage	Dent

Position	Rear-right wing
Réparation	Repair with paint
Nature du dommage	Dents

Pneus

Fonction	Additional mounted on wheel
Spécifications	WINTER
Marque	Other
Nom commercial	-
Profondeur restante des pneus	4.0 mm

Fonction	Additional not mounted
Spécifications	WINTER
Marque	Other
Nom commercial	-
Profondeur restante des pneus	4.0 mm

Fonction	Additional not mounted
Spécifications	WINTER
Marque	Other
Nom commercial	-
Profondeur restante des pneus	5.0 mm

Fonction	Additional not mounted
Spécifications	WINTER
Marque	Other
Nom commercial	-
Profondeur restante des pneus	5.0 mm

Fonction	Front Left
Spécifications	NORMAL
Marque	Other
Nom commercial	-
Profondeur restante des pneus	5.0 mm

Fonction	Front Right
Spécifications	NORMAL
Marque	Other
Nom commercial	-
Profondeur restante des pneus	5.0 mm

Fonction	Front Right
Spécifications	NORMAL
Marque	Other
Nom commercial	-
Profondeur restante des pneus	5.0 mm

Fonction	Rear Right
Spécifications	NORMAL
Marque	Other
Nom commercial	-
Profondeur restante des pneus	7.0 mm

Fonction	Rear Left
Spécifications	NORMAL
Marque	Other
Nom commercial	-
Profondeur restante des pneus	7.0 mm

Fonction	Spare Wheel
Spécifications	NORMAL
Marque	Other
Nom commercial	-
Profondeur restante des pneus	0.0 mm