



BMW X1: 1TGU852			
Vinnumber:	<b>WBAHT710205J51083</b>	Versionname:	<b>sDrive18d (100 kW)</b>
First Registrationdate:	<b>2/11/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>222379</b>	Power Kw:	<b>100</b>
Bodytype:		Body colour:	<b>Brown</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>1413</b>
Fueltype:	<b>Diesel</b>		
Maintenance:	<b>OK</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options			
Number of keys total:	<b>2</b>	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Type of headlighting:	<b>Headlighting LED</b>	Type of Tow bar:	<b>Tow bar removable</b>
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining artificial leather</b>		
Type of climate control:	<b>Autom climate control</b>		

Limited Technical Inspection

Degree of wear

225/50/18/92 H				
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>225/50 R 18 92 H</b>
Tyre type FL				<b>Summer</b>
Tyre make FL				<b>261</b>
Tyre make RL				<b>261</b>

Assistance equipment			
Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

Total cost ex VAT	<b>382,02</b>
Alloy rim RR polished, Scratch(es), Acceptable	<b>0,00</b>



Bumper trim R, Scratch(es), Acceptable	<b>0,00</b>
--	-------------



Door RR, Dent(s), Repair and paint (complete)

382,02

