



BMW 5 BERLINE: 1TCN314

Vinnumber:	WBAJE31000G592526	Versionname:	520d 140kW Eff. Dyn. Aut.
First Registrationdate:	25/09/2017	Fiscalpower:	
Expertise Mileage:	87081	Power Kw:	140
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1730
Fueltype:	Diesel		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Front parking sensors:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:		Type of Tow bar:	No Tow bar
Seats F heated:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining artificial leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

	245/45/18/92 H			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				245/45 R 18 92 H
Tyre type FL				Winter
Tyre make FL				261
Tyre make RL				261

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT 1461,78

Bumper F, Scratch(es), Repair and paint (complete) 304,99



Alloy rim RL polished, Scratch(es), Acceptable 0,00



Tailgate / Boot, Chemical polution, Polish

0,00



Bonnet, Chemical polution, Polish

0,00



Roof, Chemical polution, Polish

0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

175,00



Alloy rim RR polished, Scratch(es), Repair and paint (complete)

175,00



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)

501,80



Bumper R, Scratch(es), Repair and paint (complete)

304,99



Wing RL, Scratch(es), Acceptable

0,00

