



JAGUAR F-PACE: EG2513

Vinnumber:	SADCA2BN3JA325207	Versionname:	2.0D 177kW 4x4 Aut. R-Sport
First Registrationdate:	12/11/2018	Fiscalpower:	
Expertise Mileage:	143959	Power Kw:	1778
Bodytype:		Body colour:	Red
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2405
Fueltype:	Diesel		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Sun Roof electric:	
Cruise Control:		Panoramic roof:	
Steering wheel multifunctional:		Luggage cover:	
Seats F heated:		Front parking sensors:	
Type of headlighting:	Headlighting LED	Rear parking sensors:	
Type of GPS:	GPS big screen color	Type of Tow bar:	No Tow bar
Type of Lining:	Lining artificial leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

255/55/19/111 H			
Winter tyres:	Fr.L. Pirelli: 5 mm	Fr.R. Pirelli: 5 mm	
	Re.L. Pirelli: 5 mm	Re.R. Pirelli: 5 mm	
Tyre profile depth FL:			5.0
Tyre profile depth FR:			5.0
Tyre profile depth RL:			5.0
Tyre profile depth RR:			5.0
Tyre size FL:			255/55 R 19 111 H
Tyre type FL:			Winter
Tyre make FL:			264
Tyre make RL:			264

Assistance equipment

Emergency spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT 1684,54

Outside rear-view mirror housing R, Bad repair, Check 0,00



Door FL, Scratch(es), Repair and paint (complete) 458,42



Door RL, Scratch(es), Acceptable

0,00



Bumper F, Bad repair, Check

0,00



Wing RR, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Door FR, Scratch(es), Acceptable

0,00



Bonnet, Dent(s) and scratch(es), Repair and paint (complete)

417,70



Alloy rim FL polished, Scratch(es), Repair and paint (complete)

175,00



Door RR, Scratch(es), Repair and paint (complete)

458,42



Alloy rim RL polished, Scratch(es), Repair and paint (complete)

175,00

