



NISSAN QASHQAI: 1RDL019

Vinnumber:	SJNFAAJ11U1856815	Versionname:	1.5 DCI N-CONNECTA
First Registrationdate:	23/11/2016	Fiscalpower:	
Expertise Mileage:	138229	Power Kw:	81
Bodytype:		Body colour:	Red
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2809
Fueltype:	Diesel		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Panoramic roof:	
Cruise Control:		Luggage cover:	
Steering wheel multifunctional:		Front parking sensors:	
Type of headlighting:	Headlighting Halogen	Rear parking sensors:	
Type of GPS:	GPS big screen color	Type of Tow bar:	No Tow bar
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

215/55/18/92 H				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/55 R 18 92 H
Tyre type FL				Summer
Tyre make FL				256
Tyre make RL				256

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT 643,34

Wing trim FL, Scratch(es), Acceptable 0,00



Door FL, Dent(s), Paintless dent repair 69,30



Tailgate / Boot, Dent(s), Acceptable 0,00



Wing FR, Dent(s), Acceptable 0,00



Tailgate / Boot, Scratch(es), Acceptable 0,00



Alloy rim RR polished, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete) 138,67



Bumper trim R, Scratch(es), Smart repair 121,70



Wing FL, Bad repair, Check 0,00



Door RL, Dent(s) and scratch(es), Acceptable 0,00



Door RR, Scratch(es), Acceptable 0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 175,00



Step L, Dent(s) and scratch(es), Repair and paint (complete) 138,67



Door FR, Scratch(es), Acceptable 0,00



Wing RL, Scratch(es), Acceptable 0,00



Door FL, Chemical pollution, Acceptable 0,00

