Print

macadam vab inspection

MERCEDES A: MS5398

Vinnumber:	**WDD1771871J149458**	Versionname:	
First Registrationdate:	**17/10/2019**	Fiscalpower:	
Expertise Mileage:	**38800**	Power Kw:	**120**
Bodytype:		Body colour	**White**
Gearbox:	**Automatic**	Type of rims (mounted)	**Aluminium**
Transmission:	**Front**	Parking lot	**3633**
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**service A3 in 21 dagen**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	**No Tow bar**
Seats F heated			
Radio multimedia			
Type of headlighting	**Headlighting LED**		
Type of GPS	**GPS big screen color**		
Type of Lining	**Lining leather**		
Type of climate control	**Autom climate control**		
Type of GPS storage	**HD**		

Limited Technical Inspection

Degree of wear

	225/45/18/91 W			
Summer tyres:	Fr.L.	**Pirelli: 4 mm**	Fr.R.	**Pirelli: 4 mm**
	Re.L.	**Pirelli: 5 mm**	Re.R.	**Pirelli: 5 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**225/45 R 18 91 W**
Tyre type FL	**Summer**
Tyre make FL	**264**
Tyre make RL	**264**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**
Number of charging cables (normal)	**0**		
Number of charging cables (rapid charge)	**0**		

Total cost ex VAT	**687,32**
Interior, Dirty, Cleaning	**150,00**

Bumper F, Scratch(es), Repair and paint (complete)	283,16

Alloy rim FL polished, Scratch(es), Acceptable	0,00

Outer sill L, Scratch(es), Paint	0,00

Bumper F, Scratch(es), Repair and paint (complete)	254,16