Print

macadam vab inspection

RENAULT GRAND SCENIC: 1TBQ119

Vinnumber:	VF1RFA00158226633	Versionname:	Energy dCi 110 Bose Edition 7P
First Registrationdate:	15/09/2017	Fiscalpower:	
Expertise Mileage:	102492	Power Kw:	81
Bodytype:		Body colour	Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1332
Fueltype:	Diesel		
Maintenance	OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	Tow bar fixed
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Degree of wear

	195/55/20/92 H			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Tyre profile depth FL	5.0
Tyre profile depth FR	5.0
Tyre profile depth RL	5.0
Tyre profile depth RR	5.0
Tyre size FL	195/55 R 20 92 H
Tyre type FL	Summer
Tyre make FL	261
Tyre make RL	261

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1356,02
Rear window, Scratch(es), Replace	0,00

Door FL, Chemical polution, Repair and paint (complete)	382,02

Alloy rim FR polished, Scratch(es), Repair and paint (complete)	175,00

Alloy rim RR polished, Scratch(es), Repair and paint (complete)	175,00

Alloy rim FL polished, Scratch(es), Acceptable	0,00

Wing RL, Chemical polution, Repair and paint (complete)	369,84

Bumper R, Scratch(es), Repair and paint (complete)	254,16

Step R, Scratch(es), Acceptable	0,00