



Tesla Model Y: 2BJF237

Vinnumber:	LRWYGCEK6MC139772	Versionname:	
First Registrationdate:	6/12/2021	Fiscalpower:	
Expertise Mileage:	25074	Power Kw:	158
Bodytype:		Body colour:	White
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2607
Fueltype:	Electric		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	Yes		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Panoramic roof:	
Seats F heated:		Front parking sensors:	
Radio multimedia:		Rear parking sensors:	
Type of headlighting:	Headlighting LED	Type of Tow bar:	No Tow bar
Type of GPS:	GPS big screen color		
Type of Lining:	Lining artificial leather		
Type of climate control:	Autom climate control		
Adaptive cruise control:			

Limited Technical Inspection

Degree of wear

255/40/20/101 W				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL:				4.0
Tyre profile depth FR:				4.0
Tyre profile depth RL:				4.0
Tyre profile depth RR:				4.0
Tyre size FL:				255/40 R 20 101 W
Tyre type FL:				Summer
Tyre make FL:				261
Tyre make RL:				261

Assistance equipment

Number of charging cables (normal):	1
Number of charging cables (rapid charge):	1

Total cost ex VAT	895,56
Alloy rim FR, Scratch(es), Repair and paint (complete)	114,00



Tyre FL, Tear, Replace	184,52
-------------------------------	---------------



Tyre RL, Deformed / Strained, Replace 184,52



Tailgate / Boot, Bad repair, Check 0,00



Alloy rim FR, Scratch(es), Repair and paint (complete) 114,00



Wing RR, Bad repair, Check 0,00



Bumper F, Scratch(es), Acceptable 0,00



Alloy rim RL, Scratch(es), Repair and paint (complete) 114,00



Tyre RR, Deformed / Strained, Replace 184,52



Wing RL, Bad repair, Check 0,00

