



BMW 4 GRAN COUPE: 1RGC371

Vinnumber:	WBA4E71020G747095	Versionname:	2.0 418D (110KW) GRAN COUPE
First Registrationdate:	15/12/2016	Fiscalpower:	
Expertise Mileage:	144816	Power Kw:	110
Bodytype:		Body colour:	Dark Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1304
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	No Tow bar
Radio multimedia:			
Type of headlighting:	Headlighting Xenon		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		
Sport seats:			

Limited Technical Inspection

Degree of wear

225/45/18/91 W				
Summer tyres:	Fr.L.	Pirelli: 5,1 mm	Fr.R.	Pirelli: 5,1 mm
	Re.L.	Pirelli: 3,6 mm	Re.R.	Pirelli: 3,6 mm
Tyre profile depth FL				5.1
Tyre profile depth FR				5.1
Tyre profile depth RL				3.6
Tyre profile depth RR				3.6
Tyre size FL				225/45 R 18 91 W
Tyre type FL				Summer
Tyre make FL				264
Tyre make RL				264

Assistance equipment

Number of charging cables (normal):	0	Runflat:	Yes
Number of charging cables (rapid charge):	0		

Total cost ex VAT 965,72

Bumper F, Scratch(es), Spot repair 127,12



Alloy rim RL polished, Scratch(es), Repair and paint (complete) 175,00



Bumper R, Scratch(es), Acceptable

0,00



Wing RR, Dent(s), Acceptable

0,00



Wing FL, Scratch(es), Acceptable

0,00



Door FR, Dent(s), Paintless dent repair

69,30



Door RR, Dent(s), Paintless dent repair

69,30



Alloy rim RL polished, Rust, Repair and paint (complete)

175,00



Door FL, Scratch(es), Acceptable

0,00



Alloy rim RR polished, Scratch(es), Repair and paint (complete)

175,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

175,00



Windscreen, Stone chip(s), Acceptable

0,00

