



MERCEDES C BERLINE: 1RAZ217

Vinnumber:	WDD2050361R233962	Versionname:	1.6 C 180 D AMG LINE
First Registrationdate:	2/11/2016	Fiscalpower:	
Expertise Mileage:	126779	Power Kw:	85
Bodytype:		Body colour:	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	4506
Fueltype:	Diesel		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Front parking sensors:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

245/40/18/92 H				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				245/40 R 18 92 H
Tyre type FL				Summer
Tyre make FL				256
Tyre make RL				256

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	3193,07
Bonnet, Chemical pollution, Repair and paint (complete)	382,89



Outside rear-view mirror housing L, Scratch(es), Acceptable	0,00
--	-------------



Alloy rim RR polished, Scratch(es), Repair and paint (complete)

192,50



Rear window, Scratch(es), Acceptable

0,00



Wing FL, Scratch(es), Acceptable

0,00



Wing RL, Chemical polution, Repair and paint (complete)

406,82



Door RR, Dent(s), Acceptable

0,00



Tailgate / Boot, Chemical polution, Repair and paint (complete)

398,21



Door panel FR, Scratch(es), Smart repair

110,00



Door RL, Dent(s), Paintless dent repair

90,00



Door RR, Dent(s), Paintless dent repair

120,00



Roof, Chemical polution, Repair and paint (complete)

635,58



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

192,50



Bumper R, Scratch(es), Repair and paint (complete)

279,57



Bumper F, Scratch(es), Acceptable

0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete)

192,50



Alloy rim RL polished, Scratch(es), Repair and paint (complete)

192,50

