



**RENAULT GRAND SCENIC: 1LTF883**

Vinnumber:	<b>VF1JZ89BH54439189</b>	Versionname:	<b>1.5 ENERGY DCI 110 BOSE EDITION 7P</b>
First Registrationdate:	<b>30/11/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>150601</b>	Power Kw:	<b>81</b>
Bodytype:		Body colour:	<b>Burgundy</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>2510</b>
Fueltype:	<b>Diesel</b>		
Maintenance:	<b>OK</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Number of keys total:	<b>2</b>	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Type of headlighting:	<b>Headlighting Halogen</b>	Type of Tow bar:	<b>Tow bar fixed</b>
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining semi-artificial leather</b>		
Type of climate control:	<b>Autom climate control</b>		

**Limited Technical Inspection**

**Degree of wear**

<b>205/55/17/92 H</b>				
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>205/55 R 17 92 H</b>
Tyre type FL				<b>Summer</b>
Tyre make FL				<b>256</b>
Tyre make RL				<b>256</b>

**Assistance equipment**

Emergency spare wheel:	<b>Yes</b>	Jack:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

<b>Total cost ex VAT</b>	<b>2635,92</b>
--------------------------	----------------

<b>Door FR, Dent(s), Repair and paint (complete)</b>	<b>382,02</b>
--	---------------



<b>Alloy rim RR polished, Scratch(es), Repair and paint (complete)</b>	<b>175,00</b>
--	---------------



Door FL, Scratch(es), Acceptable 0,00



Wing FL, Bad repair, Check 0,00



Door RR, Scratch(es), Acceptable 0,00



Door RL, Scratch(es), Repair and paint (complete) 382,02



Wing RR, Dent(s), Repair and paint (complete) 456,84



Bumper R, Scratch(es), Repair and paint (complete) 254,16



Interior, Dirty, Forfeit 29,00



Seat cover FL, Damaged, Acceptable 0,00



Wing FR, Dent(s) and scratch(es), Repair and paint (complete) 293,21



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 175,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 175,00



Alloy rim RL polished, Scratch(es), Repair and paint (complete) 175,00



Step R, Scratch(es), Repair and paint (complete) 138,67



Outside rear-view mirror housing L, Scratch(es), Acceptable 0,00

