



FORD FOCUS CLIPPER: VW4376

Vinnnummer:	WF0PXXGCHPKU59158	Versionname:	2.0 EcoBlue 110kW Active Business
First Registrationdate:	4/12/2019	Fiscalpower:	
Expertise Mileage:	123163	Power Kw:	110
Bodytype:		Body colour:	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2601
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	No Tow bar
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Degree of wear

215/55/17/98 V				
Winter tyres:	Fr.L.	Michelin: 6,9 mm	Fr.R.	Michelin: 6,7 mm
	Re.L.	Semperit: 7,4 mm	Re.R.	Semperit: 6,9 mm
Tyre profile depth FL:				6.9
Tyre profile depth FR:				6.7
Tyre profile depth RL:				7.4
Tyre profile depth RR:				6.9
Tyre size FL:				215/55 R 17 98 V
Tyre type FL:				Winter
Tyre make FL:				261
Tyre make RL:				2477

Assistance equipment

Emergency spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	450,86
Bumper moulding R, Scratch(es), Smart repair:	121,70



Wing RR, Scratch(es), Paint:	0,00
------------------------------	-------------



Bonnet, Scratch(es), Polish 0,00



Bumper R, Scratch(es), Repair and paint (complete) 254,16



Door RL, Scratch(es), Acceptable 0,00



Outside rear-view mirror housing L, Scratch(es), Acceptable 0,00



Bumper F, Scratch(es), Acceptable 0,00



Door FR, Scratch(es), Acceptable 0,00



Boot lid covering R, Broken, Replace 75,00

