



<b>BMW X1: 1WDC099</b>			
Vinnumber:	<b>WBAJH710003G13514</b>	Versionname:	<b>xDrive18dA (100 kW)</b>
First Registrationdate:	<b>30/04/2019</b>	Fiscalpower:	
Expertise Mileage:	<b>81395</b>	Power Kw:	<b>100</b>
Bodytype:		Body colour:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>3532</b>
Fueltype:	<b>Diesel</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>			
Number of keys total:	<b>2</b>	Sun Roof electric:	
Cruise Control:		Panoramic roof:	
Steering wheel multifunctional:		Luggage cover:	
Seats F heated:		Front parking sensors:	
Radio multimedia:		Rear parking sensors:	
Type of headlighting:	<b>Headlighting LED</b>	Type of Tow bar:	<b>No Tow bar</b>
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining artificial leather</b>		
Type of climate control:	<b>Autom climate control</b>		
Sport seats:			
Type of GPS storage:	<b>HD</b>		

**Limited Technical Inspection**

**Degree of wear**

<b>225/50/18/99 W</b>			
Summer tyres:	Fr.L. <b>Pirelli: 4,2 mm</b>	Fr.R. <b>Pirelli: 4,3 mm</b>	
	Re.L. <b>Pirelli: 4,3 mm</b>	Re.R. <b>Pirelli: 4,2 mm</b>	
Tyre profile depth FL:			<b>4.2</b>
Tyre profile depth FR:			<b>4.3</b>
Tyre profile depth RL:			<b>4.3</b>
Tyre profile depth RR:			<b>4.2</b>
Tyre size FL:			<b>225/50 R 18 99 W</b>
Tyre type FL:			<b>Summer</b>
Tyre make FL:			<b>264</b>
Tyre make RL:			<b>264</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

Total cost ex VAT 382,02

Door RL, Scratch(es), Polish 0,00



Door FR, Dent(s) and scratch(es), Repair and paint (complete) 382,02

