



**VOLKSWAGEN ARTEON: 1UXR267**

Vinnnumber:	<b>WVWZZZ3HZJE531720</b>	Versionname:	<b>2.0 TDI SCR R-Line</b>
First Registrationdate:	<b>28/08/2018</b>	Fiscalpower:	
Expertise Mileage:	<b>232843</b>	Power Kw:	<b>110</b>
Bodytype:		Body colour:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>2304</b>
Fueltype:	<b>Diesel</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Number of keys total:	<b>2</b>	Seats electric F L:	
Steering wheel multifunctional:		Seats electric F R:	
Seats F heated:		Luggage cover:	
Radio multimedia:		Front parking sensors:	
Type of headlighting:	<b>Headlighting LED</b>	Rear parking sensors:	
Type of GPS:	<b>GPS big screen color</b>	Type of Tow bar:	<b>No Tow bar</b>
Type of Lining:	<b>Lining artificial leather</b>		
Type of climate control:	<b>Autom climate control</b>		
Adaptive cruise control:			
Sport seats:			
Type of GPS storage:	<b>HD</b>		

**Limited Technical Inspection**

**Degree of wear**

<b>245/40/19/94 V</b>			
Winter tyres:	Fr.L. <b>Pirelli: 5,4 mm</b>	Fr.R. <b>Pirelli: 5,4 mm</b>	
	Re.L. <b>Pirelli: 7,1 mm</b>	Re.R. <b>Pirelli: 7,1 mm</b>	
Tyre profile depth FL:			<b>5.4</b>
Tyre profile depth FR:			<b>5.4</b>
Tyre profile depth RL:			<b>7.1</b>
Tyre profile depth RR:			<b>7.1</b>
Tyre size FL:			<b>245/40 R 19 94 V</b>
Tyre type FL:			<b>Winter</b>
Tyre make FL:			<b>264</b>
Tyre make RL:			<b>264</b>

**Assistance equipment**

Emergency spare wheel:	<b>Yes</b>	Jack:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

Total cost ex VAT 645,49

Rear window, Scratch(es), Polish 0,00



Roof pillar R, Bad repair, Repair and paint (complete) 264,21



Rear spoiler, Scratch(es), Acceptable

0,00



Alloy rim FR polished, Scratch(es), Acceptable

0,00



Bumper F, Stone chip(s), Repair and paint (complete)

254,16



Windscreen, Stone chip(s), Acceptable

0,00



Bonnet, Dent(s), Acceptable

0,00



Alloy rim FL polished, Scratch(es), Acceptable

0,00



Wing RL, Chemical polution, Spot repair

127,12

