



PEUGEOT 308 SW: 1RBS417

Vinnumber:	VF3LCBHXHGS278433	Versionname:	1.6 BLUEHDI 85KW S/S 85G ACTIVE
First Registrationdate:	8/11/2016	Fiscalpower:	
Expertise Mileage:	120620	Power Kw:	85
Bodytype:		Body colour:	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1310
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:		Type of Tow bar:	No Tow bar
Radio multimedia:			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Degree of wear

205/55/16/91 V			
Summer tyres:	Fr.L. Vredestein: 4,2 mm	Fr.R. Vredestein: 4,2 mm	
	Re.L. Michelin: 4,6 mm	Re.R. Michelin: 4,6 mm	
Tyre profile depth FL:			4.2
Tyre profile depth FR:			4.2
Tyre profile depth RL:			4.6
Tyre profile depth RR:			4.6
Tyre size FL:			205/55 R 16 91 V
Tyre type FL:			Summer
Tyre make FL:			2480
Tyre make RL:			261

Assistance equipment

Emergency spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT 934,11

Wing RR, Scratch(es), Acceptable 0,00



Outer sill R, Dent(s), Repair and paint (complete) 372,60



Roof pillar R, Scratch(es), Polish

0,00



Alloy rim FR, Scratch(es), Repair and paint (complete)

114,00



Tailgate / Boot, Scratch(es), Acceptable

0,00



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)

264,21



Bonnet, Stone chip(s), Acceptable

0,00



Door FL, Scratch(es), Polish

0,00



Alloy rim FL, Scratch(es), Repair and paint (complete)

114,00



Door RL, Dent(s), Paintless dent repair

69,30



Bumper R, Scratch(es), Acceptable

0,00



Alloy rim RR, Scratch(es), Acceptable

0,00



Wing FL, Scratch(es), Polish

0,00



Wing RL, Scratch(es), Polish

0,00

