



| | | | |
|------------------------------------|--------------------------|-------------------------|------------------------------|
| BMW X1: 1UUN885 | | | |
| Vinnumber: | WBAHT710505K85702 | Versionname: | 2.0 SDRIVE18D (100KW) |
| First Registrationdate: | 30/07/2018 | Fiscalpower: | |
| Expertise Mileage: | 101196 | Power Kw: | 100 |
| Bodytype: | | Body colour: | Beige |
| Gearbox: | MAN 6 VIT | Type of rims (mounted): | Aluminium |
| Transmission: | | Parking lot: | 2705 |
| Fueltype: | Diesel | | |
| Type of rims (mounted): | Aluminium | | |
| Certificate of Conformity: | Yes | | |
| Category: | Passenger Car | | |
| Registration Certificate Car (BE): | Yes | | |

| | | | |
|---------------------------------|----------------------------------|------------------------|-------------------|
| Options | | | |
| Number of keys total: | 2 | Sun Roof electric: | |
| Cruise Control: | | Panoramic roof: | |
| Steering wheel multifunctional: | | Luggage cover: | |
| Seats F heated: | | Front parking sensors: | |
| Radio multimedia: | | Rear parking sensors: | |
| Type of headlighting: | Headlighting Halogen | Type of Tow bar: | No Tow bar |
| Type of GPS: | GPS big screen color | | |
| Type of Lining: | Lining artificial leather | | |
| Type of climate control: | Autom climate control | | |
| Type of GPS storage: | HD | | |

Limited Technical Inspection

Degree of wear

| | | | |
|------------------------|-----------------------------|-----------------------------|-------------------------|
| 225/55/17/98 V | | | |
| Winter tyres: | Fr.L. Dunlop: 4,8 mm | Fr.R. Dunlop: 4,8 mm | |
| | Re.L. Dunlop: 6,2 mm | Re.R. Dunlop: 6,2 mm | |
| Tyre profile depth FL: | | | 4.8 |
| Tyre profile depth FR: | | | 4.8 |
| Tyre profile depth RL: | | | 6.2 |
| Tyre profile depth RR: | | | 6.2 |
| Tyre size FL: | | | 225/55 R 17 98 V |
| Tyre type FL: | | | Winter |
| Tyre make FL: | | | 257 |
| Tyre make RL: | | | 257 |

Assistance equipment

| | | | |
|---|------------|-------------|------------|
| Repair kit: | Yes | Compressor: | Yes |
| Number of charging cables (normal): | 0 | | |
| Number of charging cables (rapid charge): | 1 | | |

| | |
|-------------------|------|
| Total cost ex VAT | 0,00 |
|-------------------|------|

| | |
|----------------------------------|------|
| Door RL, Scratch(es), Acceptable | 0,00 |
|----------------------------------|------|



| | |
|----------------------------------|------|
| Wing FL, Scratch(es), Acceptable | 0,00 |
|----------------------------------|------|

