



MERCEDES C BREAK: 1VMR413

Vinnumber:	WDD2052111F846201	Versionname:	C 200 d Business Solution Auto
First Registrationdate:	2/01/2019	Fiscalpower:	
Expertise Mileage:	68727	Power Kw:	110
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3502
Fueltype:	Petrol		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	Yes		

Options

Number of keys total	1	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			
Type of GPS storage	SD present		

Limited Technical Inspection

Degree of wear

255/45/18/95 V			
Winter tyres:	Fr.L. Kleber: 5,7 mm	Fr.R. Kleber: 5,7 mm	
	Re.L. Pirelli: 5,3 mm	Re.R. Pirelli: 6 mm	
Tyre profile depth FL			5.7
Tyre profile depth FR			5.7
Tyre profile depth RL			5.3
Tyre profile depth RR			6.0
Tyre size FL			255/45 R 18 95 V
Tyre type FL			Winter
Tyre make FL			2479
Tyre make RL			264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	147,80
Ignition key, Missing, Replace	0,00



Door panel RL, Scratch(es), Replace 147,80



Alloy rim RR polished, Scratch(es), Acceptable 0,00



Step L, Dent(s), Acceptable 0,00



Bumper R, Scratch(es), Polish 0,00



Wing RR, Dent(s), Acceptable 0,00



Roof, Dent(s), Acceptable 0,00



Bumper F, Dent(s) and scratch(es), Repair and paint (complete) 0,00



Bonnet, Dent(s) and scratch(es), Repair and paint (complete) 0,00

