



**RENAULT CLIO: 1SLP232**

|                                    |                          |                         |                              |
|------------------------------------|--------------------------|-------------------------|------------------------------|
| Vinnumber:                         | <b>VF15RBJ0D57775920</b> | Versionname:            | <b>1.5 ENERGY DCI 90 ZEN</b> |
| First Registrationdate:            | <b>8/06/2017</b>         | Fiscalpower:            |                              |
| Expertise Mileage:                 | <b>101218</b>            | Power Kw:               | <b>66</b>                    |
| Bodytype:                          |                          | Body colour:            | <b>Red</b>                   |
| Gearbox:                           | <b>Automatic</b>         | Type of rims (mounted): | <b>Aluminium</b>             |
| Transmission:                      |                          | Parking lot:            | <b>2722</b>                  |
| Fueltype:                          | <b>Diesel</b>            |                         |                              |
| Type of rims (mounted):            | <b>Aluminium</b>         |                         |                              |
| Certificate of Conformity:         | <b>Yes</b>               |                         |                              |
| Category:                          | <b>Passenger Car</b>     |                         |                              |
| Registration Certificate Car (BE): | <b>Yes</b>               |                         |                              |

**Options**

|                                 |                               |                       |                   |
|---------------------------------|-------------------------------|-----------------------|-------------------|
| Number of keys total:           | <b>1</b>                      | Luggage cover:        |                   |
| Cruise Control:                 |                               | Rear parking sensors: |                   |
| Steering wheel multifunctional: |                               | Type of Tow bar:      | <b>No Tow bar</b> |
| Radio multimedia:               |                               |                       |                   |
| Type of headlighting:           | <b>Headlighting Halogen</b>   |                       |                   |
| Type of GPS:                    | <b>GPS big screen color</b>   |                       |                   |
| Type of Lining:                 | <b>Lining fabrics</b>         |                       |                   |
| Type of climate control:        | <b>Manual climate control</b> |                       |                   |
| Type of GPS storage:            | <b>HD</b>                     |                       |                   |

**Limited Technical Inspection**

**Degree of wear**

|                        |                               |                               |                         |
|------------------------|-------------------------------|-------------------------------|-------------------------|
| <b>195/55/16/91 H</b>  |                               |                               |                         |
| Summer tyres:          | Fr.L. <b>Michelin: 6,2 mm</b> | Fr.R. <b>Michelin: 6,2 mm</b> |                         |
|                        | Re.L. <b>Michelin: 4,8 mm</b> | Re.R. <b>Michelin: 4,8 mm</b> |                         |
| Tyre profile depth FL: |                               |                               | <b>6.2</b>              |
| Tyre profile depth FR: |                               |                               | <b>6.2</b>              |
| Tyre profile depth RL: |                               |                               | <b>4.8</b>              |
| Tyre profile depth RR: |                               |                               | <b>4.8</b>              |
| Tyre size FL:          |                               |                               | <b>195/55 R 16 91 H</b> |
| Tyre type FL:          |                               |                               | <b>All season</b>       |
| Tyre make FL:          |                               |                               | <b>261</b>              |
| Tyre make RL:          |                               |                               | <b>261</b>              |

**Assistance equipment**

|   |            |             |            |
|---|------------|-------------|------------|
| Repair kit:                               | <b>Yes</b> | Compressor: | <b>Yes</b> |
| Number of charging cables (normal):       | <b>0</b>   |             |            |
| Number of charging cables (rapid charge): | <b>0</b>   |             |            |

|                    |               |
|--------------------|---------------|
| Total cost ex VAT: | <b>514,80</b> |
|--------------------|---------------|

|                                   |             |
|-----------------------------------|-------------|
| Wing RR, Scratch(es), Acceptable: | <b>0,00</b> |
|-----------------------------------|-------------|



|   |             |
|---|-------------|
| Door RR, Dent(s) and scratch(es), Acceptable: | <b>0,00</b> |
|---|-------------|



Alloy rim FL, Scratch(es), Acceptable 0,00



Wing FR, Scratch(es), Paint (partial) 0,00



Bumper R, Scratch(es), Acceptable 0,00



Door RL, Scratch(es), Acceptable 0,00



Ignition key, Missing, Replace 264,00



Wing RL, Dent(s) and scratch(es), Acceptable 0,00



Alloy rim RR, Scratch(es), Repair and paint (complete) 125,40



Alloy rim FR, Scratch(es), Repair and paint (complete) 125,40

