



**Peugeot 5008: 1UAR286**

Vinnumber:	<b>VF3MCYHZJL016379</b>	Versionname:	
First Registrationdate:	<b>15/03/2018</b>	Fiscalpower:	
Expertise Mileage:	<b>134576</b>	Power Kw:	<b>96</b>
Bodytype:		Body colour:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>2512</b>
Fueltype:	<b>Diesel</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

**Options**

Number of keys total:	<b>2</b>	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	<b>Tow bar removable</b>
Type of headlighting:	<b>Headlighting Halogen</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining fabrics</b>		
Type of climate control:	<b>Autom climate control</b>		

**Limited Technical Inspection**

**Degree of wear**

<b>215/65/17/99 H</b>			
Winter tyres:	Fr.L. <b>Continental: 4 mm</b>	Fr.R. <b>Continental: 4 mm</b>	
	Re.L. <b>Continental: 4 mm</b>	Re.R. <b>Continental: 4 mm</b>	
Tyre profile depth FL:			<b>4.0</b>
Tyre profile depth FR:			<b>4.0</b>
Tyre profile depth RL:			<b>4.0</b>
Tyre profile depth RR:			<b>4.0</b>
Tyre size FL:			<b>215/65 R 17 99 H</b>
Tyre type FL:			<b>Winter</b>
Tyre make FL:			<b>256</b>
Tyre make RL:			<b>256</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

<b>Total cost ex VAT</b>	<b>1459,26</b>
--------------------------	----------------

<b>Door trim RL, Scratch(es), Acceptable</b>	<b>0,00</b>
----------------------------------------------	-------------



<b>Tailgate / Boot, Scratch(es), Acceptable</b>	<b>0,00</b>
-------------------------------------------------	-------------



Alloy rim FR, Scratch(es), Acceptable 0,00



Wing RL, Scratch(es), Spot repair 139,83



Wing trim RL, Scratch(es), Replace 108,20



Bonnet, Scratch(es), Acceptable 0,00



Rear window, Scratch(es), Acceptable 0,00



Door RL, Scratch(es), Spot repair 139,83



Headlight L, Bad repair, Check 0,00



Roof, Chemical pollution, Repair and paint (complete) 635,58



Wing RR, Dent(s) and scratch(es), Repair and paint (complete) 435,82

