


RENAULT CLIO: 1VSK730

Vinnumber:	VF1R9800162568071	Versionname:	TCe 90 Corporate Edition
First Registrationdate:	14/02/2019	Fiscalpower:	
Expertise Mileage:	87429	Power Kw:	66
Bodytype:		Body colour:	Silver
Gearbox:	MAN 5 VIT	Type of rims (mounted):	Steel
Transmission:		Parking lot:	4506
Fueltype:	Petrol		
Maintenance:	OK		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Rear parking sensors:	
Steering wheel multifunctional:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		

Limited Technical Inspection
Degree of wear

195/55/16/92 H				
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL		5.0		
Tyre profile depth FR		5.0		
Tyre profile depth RL		5.0		
Tyre profile depth RR		5.0		
Tyre size FL		195/55 R 16 92 H		
Tyre type FL		Winter		
Tyre make FL		261		
Tyre make RL		261		

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	2061,84
Door RR, Dent(s) and scratch(es), Repair and paint (complete)	394,17



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)	499,45
---	---------------



Bumper F, Scratch(es), Acceptable

0,00



Wheel cover RL, Scratch(es), Replace

31,68



Bumper R, Scratch(es), Acceptable

0,00



Tyre FR, Deformed / Strained, Acceptable

0,00



Wheel cover FR, Scratch(es), Replace

31,68



Door FR, Dent(s), Acceptable

0,00



Wing RL, Scratch(es), Acceptable

0,00



Wheel cover FL, Scratch(es), Replace

31,68



Wheel cover RR, Scratch(es), Replace

31,68



Roof, Chemical pollution, Repair and paint (complete)

508,46



Door trim RR, Scratch(es), Replace	124,04
------------------------------------	--------



Headlight R, Scratch(es), Polish	0,00
----------------------------------	------



Rear window, Scratch(es), Replace	409,00
-----------------------------------	--------

