



Mercedes C: 1VLK984

Vinnumber:	WDD2050111R472460	Versionname:	
First Registrationdate:	17/12/2018	Fiscalpower:	
Expertise Mileage:	157484	Power Kw:	110
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	4331
Fueltype:	Diesel		
Maintenance	OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather and alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Degree of wear

	245/40/18/92 H			
Winter tyres:	Fr.L.	Semperit: 5 mm	Fr.R.	Semperit: 5 mm
	Re.L.	Semperit: 5 mm	Re.R.	Semperit: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				245/40 R 18 92 H
Tyre type FL				Winter
Tyre make FL				2477
Tyre make RL				2477

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	770,00
Alloy rim RR polished, Scratch(es), Repair and paint (complete)	192,50



Alloy rim FL polished, Scratch(es), Repair and paint (complete)	192,50
---	---------------



Bumper R, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00



Wing RR, Scratch(es), Acceptable

0,00



Bonnet, Scratch(es), Acceptable

0,00



Alloy rim RL polished, Scratch(es), Repair and paint (complete)

192,50



Tailgate / Boot, Scratch(es), Acceptable

0,00



Wing RL, Bad repair, Check

0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

192,50

