



BMW 5 TOURING: 1KXE219			
Vinnumber:	WBA5L51070G220779	Versionname:	2.0 520D (140KW) XDRIVE AUTO TOURING
First Registrationdate:	22/07/2015	Fiscalpower:	
Expertise Mileage:	165453	Power Kw:	140
Bodytype:		Body colour	Dark Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	4833
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options			
Number of keys total	1	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Sun Roof electric	
Seats F heated		Panoramic roof	
Radio multimedia		Luggage cover	
Type of headlighting	Headlighting Xenon	Front parking sensors	
Type of GPS	GPS big screen color	Rear parking sensors	
Type of Lining	Lining artificial leather	Type of Tow bar	No Tow bar
Type of climate control	Autom climate control		

Limited Technical Inspection

Degree of wear

	245/45/18/96 Y			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				245/45 R 18 96 Y
Tyre type FL				Summer
Tyre make FL				255
Tyre make RL				255

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1940,64
-------------------	----------------

Outer sill R, Scratch(es), Repair and paint (complete)	491,83
--	---------------



Bumper R, Scratch(es), Repair and paint (complete)	335,48
--	---------------



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------



Tailgate / Boot, Scratch(es), Acceptable	0,00
--	------



Ignition key, Missing, Replace	396,00
--------------------------------	--------

No pictures to display

Alloy rim FR polished, Scratch(es), Repair and paint (complete)	192,50
---	--------



Wing FL, Scratch(es), Spot repair	139,83
-----------------------------------	--------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim FL polished, Scratch(es), Repair and paint (complete)	192,50
---	--------



Alloy rim RR polished, Scratch(es), Repair and paint (complete)	192,50
---	--------

