



BMW 3 BERLINE: 1VDP607

Vinnumber:	WBA8C31090A815556	Versionname:	318d (110 kW)
First Registrationdate:	4/10/2018	Fiscalpower:	
Expertise Mileage:	53763	Power Kw:	110
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3819
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Degree of wear

Winter tyres:	225/50/17/94 H			
	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				225/50 R 17 94 H
Tyre type FL				Winter
Tyre make FL				261
Tyre make RL				261

Assistance equipment

Number of charging cables (normal)	0	Runflat	No
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1232,01
Door RR, Dent(s), Acceptable	0,00



Alloy rim RL, Scratch(es), Repair and paint (complete)

125,40



Door RL, Dent(s) and scratch(es), Repair and paint (complete)	420,22
---	--------



Wing RR, Dent(s), Repair and paint (complete)	406,82
---	--------



Bumper F, Scratch(es), Repair and paint (complete)	279,57
--	--------



Door FL, Scratch(es), Touch up	0,00
--------------------------------	------

