



|                                    |                   |                        |           |
|------------------------------------|-------------------|------------------------|-----------|
| BMW 4 Gran Coupé: JE5126           |                   |                        |           |
| Vinnumber:                         | WBA4K31050BP38597 | Versionname:           |           |
| First Registrationdate:            | 24/09/2018        | Fiscalpower:           |           |
| Expertise Mileage:                 | 92272             | Power Kw:              | 140       |
| Bodytype:                          |                   | Body colour            | Black     |
| Gearbox:                           | Automatic         | Type of rims (mounted) | Aluminium |
| Transmission:                      |                   | Parking lot            | 1229      |
| Fueltype:                          | Diesel            |                        |           |
| Maintenance                        | OK                |                        |           |
| Type of rims (mounted)             | Aluminium         |                        |           |
| Certificate of Conformity          | Yes               |                        |           |
| Category                           | Passenger Car     |                        |           |
| Registration Certificate Car (BE)  | Yes               |                        |           |
| Registration Certificate Home (BE) | No                |                        |           |

|                                |                           |                       |            |
|--------------------------------|---------------------------|-----------------------|------------|
| Options                        |                           |                       |            |
| Number of keys total           | 2                         | Luggage cover         |            |
| Cruise Control                 |                           | Front parking sensors |            |
| Steering wheel multifunctional |                           | Rear parking sensors  |            |
| Radio multimedia               |                           | Type of Tow bar       | No Tow bar |
| Type of headlighting           | Headlighting LED          |                       |            |
| Type of GPS                    | GPS big screen color      |                       |            |
| Type of Lining                 | Lining artificial leather |                       |            |
| Type of climate control        | Autom climate control     |                       |            |
| Type of GPS storage            | HD                        |                       |            |

Limited Technical Inspection

Degree of wear

|                       |       |                |       |                  |
|-----------------------|-------|----------------|-------|------------------|
| 225/45/18/95 V        |       |                |       |                  |
| Winter tyres:         | Fr.L. | Michelin: 3 mm | Fr.R. | Michelin: 3 mm   |
|                       | Re.L. | Michelin: 3 mm | Re.R. | Michelin: 3 mm   |
| Tyre profile depth FL |       |                |       | 3.0              |
| Tyre profile depth FR |       |                |       | 3.0              |
| Tyre profile depth RL |       |                |       | 3.0              |
| Tyre profile depth RR |       |                |       | 3.0              |
| Tyre size FL          |       |                |       | 225/45 R 18 95 V |
| Tyre type FL          |       |                |       | Winter           |
| Tyre make FL          |       |                |       | 261              |
| Tyre make RL          |       |                |       | 261              |

Assistance equipment

|                                          |   |         |     |
|------------------------------------------|---|---------|-----|
| Number of charging cables (normal)       | 0 | Runflat | Yes |
| Number of charging cables (rapid charge) | 0 |         |     |

|                   |         |
|-------------------|---------|
| Total cost ex VAT | 1002,98 |
|-------------------|---------|

|                                                                 |        |
|-----------------------------------------------------------------|--------|
| Alloy rim RR polished, Scratch(es), Repair and paint (complete) | 192,50 |
|-----------------------------------------------------------------|--------|



|                                      |      |
|--------------------------------------|------|
| Roof, Chemical pollution, Acceptable | 0,00 |
|--------------------------------------|------|



|                                                                 |        |
|-----------------------------------------------------------------|--------|
| Alloy rim FL polished, Scratch(es), Repair and paint (complete) | 192,50 |
|-----------------------------------------------------------------|--------|



|                                                    |        |
|----------------------------------------------------|--------|
| Bumper F, Scratch(es), Repair and paint (complete) | 335,48 |
|----------------------------------------------------|--------|



|                                                                 |        |
|-----------------------------------------------------------------|--------|
| Alloy rim RL polished, Scratch(es), Repair and paint (complete) | 192,50 |
|-----------------------------------------------------------------|--------|



|                                         |       |
|-----------------------------------------|-------|
| Door FL, Dent(s), Paintless dent repair | 90,00 |
|-----------------------------------------|-------|



|                              |      |
|------------------------------|------|
| Door RR, Dent(s), Acceptable | 0,00 |
|------------------------------|------|

