



RENAULT KADJAR: 1RFU462

Vinnumber:	VF1RFE00657038980	Versionname:	1.5 Energy dCi 110 Bose® Edition Eco2
First Registrationdate:	13/12/2016	Fiscalpower:	
Expertise Mileage:	127333	Power Kw:	81
Bodytype:		Body colour	Dark Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3523
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Panoramic roof	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Degree of wear

225/45/19/92 W				
Winter tyres:	Fr.L.	Bridgestone: 6,2 mm	Fr.R.	Bridgestone: 6,2 mm
	Re.L.	Bridgestone: 6,8 mm	Re.R.	Bridgestone: 6,8 mm
Tyre profile depth FL				6.2
Tyre profile depth FR				6.2
Tyre profile depth RL				6.8
Tyre profile depth RR				6.8
Tyre size FL				225/45 R 19 92 W
Tyre type FL				Winter
Tyre make FL				255
Tyre make RL				255

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1074,52
Seat cover FL, Worn, Acceptable	0,00



Backrest cover FR, Tear, Replace	461,80
----------------------------------	---------------



Wing FL, Scratch(es), Acceptable

0,00



Interior covering A pillar L, Bad repair, Check

0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

192,50



Wing FR, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00



Door RL, Scratch(es), Repair and paint (complete)

420,22



Door RR, Dent(s) and scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Roof liner, Stain, Acceptable

0,00

