



|                                    |                   |                        |               |
|------------------------------------|-------------------|------------------------|---------------|
| RENAULT CLIO: 1VMT747              |                   |                        |               |
| Vinnumber:                         | VF1R9800661767476 | Versionname:           | TCe 90 Intens |
| First Registrationdate:            | 3/01/2019         | Fiscalpower:           |               |
| Expertise Mileage:                 | 43845             | Power Kw:              | 66            |
| Bodytype:                          |                   | Body colour            | Black         |
| Gearbox:                           | MAN 5 VIT         | Type of rims (mounted) | Aluminium     |
| Transmission:                      |                   | Parking lot            | 1406          |
| Fueltype:                          | Petrol            |                        |               |
| Maintenance                        | OK                |                        |               |
| Type of rims (mounted)             | Aluminium         |                        |               |
| Certificate of Conformity          | Yes               |                        |               |
| Category                           | Passenger Car     |                        |               |
| Registration Certificate Car (BE)  | Yes               |                        |               |
| Registration Certificate Home (BE) | Yes               |                        |               |

|                                |                       |                       |            |
|--------------------------------|-----------------------|-----------------------|------------|
| Options                        |                       |                       |            |
| Number of keys total           | 2                     | Luggage cover         |            |
| Cruise Control                 |                       | Front parking sensors |            |
| Steering wheel multifunctional |                       | Rear parking sensors  |            |
| Seats F heated                 |                       | Type of Tow bar       | No Tow bar |
| Radio multimedia               |                       |                       |            |
| Type of headlighting           | Headlighting LED      |                       |            |
| Type of GPS                    | GPS big screen color  |                       |            |
| Type of Lining                 | Lining fabrics        |                       |            |
| Type of climate control        | Autom climate control |                       |            |
| Type of GPS storage            | SD present            |                       |            |

Limited Technical Inspection

Degree of wear

|                       |                |                  |       |                  |
|-----------------------|----------------|------------------|-------|------------------|
| Winter tyres:         | 195/65/16/91 H |                  |       |                  |
|                       | Fr.L.          | Uniroyal: 7,7 mm | Fr.R. | Uniroyal: 7,8 mm |
|                       | Re.L.          | Uniroyal: 8,6 mm | Re.R. | Uniroyal: 8,5 mm |
|                       |                |                  |       |                  |
| Tyre profile depth FL |                |                  |       | 7.7              |
| Tyre profile depth FR |                |                  |       | 7.8              |
| Tyre profile depth RL |                |                  |       | 8.6              |
| Tyre profile depth RR |                |                  |       | 8.5              |
| Tyre size FL          |                |                  |       | 195/65 R 16 91 H |
| Tyre type FL          |                |                  |       | Winter           |
| Tyre make FL          |                |                  |       | 265              |
| Tyre make RL          |                |                  |       | 265              |

Assistance equipment

|                                          |     |      |     |
|------------------------------------------|-----|------|-----|
| Emergency spare wheel                    | Yes | Jack | Yes |
| Number of charging cables (normal)       | 0   |      |     |
| Number of charging cables (rapid charge) | 0   |      |     |

|                                                                |        |
|----------------------------------------------------------------|--------|
| Total cost ex VAT                                              | 349,05 |
| Bumper F, Dent(s) and scratch(es), Repair and paint (complete) | 223,65 |





|                                                           |      |
|-----------------------------------------------------------|------|
| Tailgate / Boot, Not original part, Sticker removal small | 0,00 |
|-----------------------------------------------------------|------|



|                                                        |        |
|--------------------------------------------------------|--------|
| Alloy rim FR, Scratch(es), Repair and paint (complete) | 125,40 |
|--------------------------------------------------------|--------|



|                              |      |
|------------------------------|------|
| Wing RL, Scratch(es), Polish | 0,00 |
|------------------------------|------|



|                                  |      |
|----------------------------------|------|
| Wing RR, Scratch(es), Acceptable | 0,00 |
|----------------------------------|------|

