


RENAULT TALISMAN GRANDTOUR: 1TQK172

Vinnumber:	VF1RFD00059781634	Versionname:	Energy dCi 130 EDC Intens
First Registrationdate:	12/01/2018	Fiscalpower:	
Expertise Mileage:	140186	Power Kw:	96
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2514
Fueltype:	Diesel		
Maintenance	OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
TV/DVD screen F		Front parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Type of GPS storage	SD present		

Limited Technical Inspection
Degree of wear

225/55/17/101 H				
Winter tyres:	Fr.L.	BF Goodrich: 5 mm	Fr.R.	BF Goodrich: 4 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				4.0
Tyre profile depth RL				3.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 17 101 H
Tyre type FL				Winter
Tyre make FL				2485
Tyre make RL				261

Assistance equipment

Spare wheel	Yes	Jack	Yes
Emergency spare wheel	Yes		
Repair kit	Yes		
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1093,83
Door FL, Dent(s) and scratch(es), Acceptable	0,00



Seat cover FL, Worn, Acceptable

0,00



Step R, Scratch(es), Acceptable

0,00



Outside rear-view mirror cover R (upper), Scratch(es), Acceptable

0,00



Door RR, Scratch(es), Repair and paint (complete)

504,26



Wing RL, Scratch(es), Acceptable

0,00



Internal boot lining L, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00



Bonnet, Scratch(es), Acceptable

0,00



Internal boot lining R, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Step R, Scratch(es), Repair and paint (complete)

152,53



Wing RR, Scratch(es), Acceptable

0,00



Floor covering FL, Hole, Replace

327,04



Boot lid covering R, Scratch(es), Smart repair

110,00



Windscreen, Stone chip(s), Acceptable

0,00



Rear spoiler, Scratch(es), Acceptable

0,00



Wing RL, Dent(s) and scratch(es), Acceptable

0,00



Roof pillar R, Scratch(es), Acceptable

0,00



Outer door handle FR, Scratch(es), Acceptable

0,00



Roof, Hail damage, Paintless dent repair (hail)

0,00

