



**AUDI A3 SPORTBACK: 1UPP097**

Vinnumber:	<b>WAUZZZ8V0JA139345</b>	Versionname:	<b>1.0 TFSi 85kW S tronic</b>
First Registrationdate:	<b>2/07/2018</b>	Fiscalpower:	
Expertise Mileage:	<b>129250</b>	Power Kw:	<b>85</b>
Bodytype:		Body colour:	<b>Dark Blue</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>3718</b>
Fueltype:	<b>Diesel</b>		
Maintenance:	<b>OK</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>Yes</b>		

**Options**

Number of keys total:	<b>2</b>	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	<b>No Tow bar</b>
Type of headlighting:	<b>Headlighting Xenon</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining fabrics</b>		
Type of climate control:	<b>Autom climate control</b>		
Adaptive cruise control:			
Type of GPS storage:	<b>SD present</b>		

**Limited Technical Inspection**

**Degree of wear**

<b>205/55/16/91 H</b>				
Winter tyres:	Fr.L.	<b>Semperit: 7,3 mm</b>	Fr.R.	<b>Semperit: 7,2 mm</b>
	Re.L.	<b>Continental: 7,4 mm</b>	Re.R.	<b>Continental: 7 mm</b>
Tyre profile depth FL:				<b>7.3</b>
Tyre profile depth FR:				<b>7.2</b>
Tyre profile depth RL:				<b>7.4</b>
Tyre profile depth RR:				<b>7.0</b>
Tyre size FL:				<b>205/55 R 16 91 H</b>
Tyre type FL:				<b>Winter</b>
Tyre make FL:				<b>2477</b>
Tyre make RL:				<b>256</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>No</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

<b>Total cost ex VAT</b>	<b>388,30</b>
<b>Wing RR, Dent(s), Acceptable</b>	<b>0,00</b>



Alloy rim RL, Scratch(es), Repair and paint (complete)

125,40



Alloy rim FL, Scratch(es), Repair and paint (complete)

125,40



Boot carpet, Waterinfiltration, Cleaning

27,50



Door RR, Scratch(es), Paint

0,00



Bumper R, Scratch(es), Paint

0,00



Bumper F, Scratch(es), Smart repair

110,00



Compressor, Missing, Replace

0,00

