



CITROËN GRAND C4 SPACETOURER: ZJ5902

| | | | |
|------------------------------------|--------------------------|-------------------------|---|
| Vinnumber: | VF73AYHZPKJ555671 | Versionname: | 1.5 BlueHDi 130 S&S MAN6 Business Lounge |
| First Registrationdate: | 27/02/2019 | Fiscalpower: | |
| Expertise Mileage: | 89786 | Power Kw: | 96 |
| Bodytype: | | Body colour: | Anthracite |
| Gearbox: | MAN 6 VIT | Type of rims (mounted): | Aluminium |
| Transmission: | | Parking lot: | 1515 |
| Fueltype: | Diesel | | |
| Type of rims (mounted): | Aluminium | | |
| Certificate of Conformity: | Yes | | |
| Category: | Passenger Car | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|---------------------------------|----------------------------------|------------------------|-------------------|
| Number of keys total: | 2 | Seats electric F L: | |
| Cruise Control: | | Seats electric F R: | |
| Steering wheel multifunctional: | | Luggage cover: | |
| Seats F heated: | | Front parking sensors: | |
| Radio multimedia: | | Rear parking sensors: | |
| Type of headlighting: | Headlighting Halogen | Type of Tow bar: | No Tow bar |
| Type of GPS: | GPS big screen color | | |
| Type of Lining: | Lining artificial leather | | |
| Type of climate control: | Autom climate control | | |
| Type of GPS storage: | HD | | |

Limited Technical Inspection

Degree of wear

| | | | | |
|-----------------------|-----------------------|----------------------------|-------|----------------------------|
| | 205/55/17/95 W | | | |
| Winter tyres: | Fr.L. | Continental: 3,2 mm | Fr.R. | Continental: 3,2 mm |
| | Re.L. | Continental: 6,8 mm | Re.R. | Continental: 6,8 mm |
| Tyre profile depth FL | | | | 3.2 |
| Tyre profile depth FR | | | | 3.2 |
| Tyre profile depth RL | | | | 6.8 |
| Tyre profile depth RR | | | | 6.8 |
| Tyre size FL | | | | 205/55 R 17 95 W |
| Tyre type FL | | | | Winter |
| Tyre make FL | | | | 256 |
| Tyre make RL | | | | 256 |

Assistance equipment

| | | | |
|---|------------|-------|------------|
| Spare wheel: | Yes | Jack: | Yes |
| Number of charging cables (normal): | 0 | | |
| Number of charging cables (rapid charge): | 0 | | |

Total cost ex VAT 597,47

Alloy rim RR polished, Rust, Acceptable 0,00



Door RR, Dent(s), Acceptable 0,00



| | |
|----------------------------------|------|
| Door RL, Scratch(es), Acceptable | 0,00 |
|----------------------------------|------|



| | |
|--|--------|
| Bumper F, Scratch(es), Repair and paint (complete) | 279,57 |
|--|--------|



| | |
|---|--------|
| Alloy rim FR polished, Scratch(es), Repair and paint (complete) | 192,50 |
|---|--------|



| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|



| | |
|----------------------------------|------|
| Door FR, Scratch(es), Acceptable | 0,00 |
|----------------------------------|------|



| | |
|--|--------|
| Alloy rim RL, Scratch(es), Repair and paint (complete) | 125,40 |
|--|--------|

