



TOYOTA AURIS: 1VPM810			
Vinnumber:	SB1MS3JEX0E399580	Versionname:	1.8 VVT-i Hybrid CVT Style
First Registrationdate:	18/01/2019	Fiscalpower:	
Expertise Mileage:	72615	Power Kw:	73
Bodytype:		Body colour:	Beige
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2105
Fueltype:	Hybrid Petrol		
Maintenance:	OK		
Maintenance:	réalisé à 61397 km le 24/06/22		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options			
Number of keys total:	2	Luggage cover:	
Cruise Control:		Type of Tow bar:	No Tow bar
Steering wheel multifunctional:			
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	No GPS		
Type of Lining:	Lining semi-Alcantara		
Type of climate control:	Autom climate control		
Type of GPS storage:	N.A.		

Limited Technical Inspection

Degree of wear

225/45/17/91 H				
Winter tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 7 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				6.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				225/45 R 17 91 H
Tyre type FL				Winter
Tyre make FL				2480
Tyre make RL				2480

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT **588,07**

Alloy rim FR polished, Scratch(es), Acceptable **0,00**



Engine insulation, Tear, Replace

0,00



Alloy rim FL polished, Scratch(es), Acceptable

0,00



Bonnet, Scratch(es), Acceptable

0,00



Alloy rim RL polished, Scratch(es), Acceptable

0,00



Alloy rim RR polished, Scratch(es), Repair and paint (complete)

192,50



Bumper F, Dent(s), Acceptable

0,00



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)

395,57

