



VOLVO V60: 1V5F747			
Vinnumber:	YV1ZW72V1K2328563	Versionname:	D3 Momentum
First Registrationdate:	13/02/2019	Fiscalpower:	
Expertise Mileage:	84507	Power Kw:	110
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2511
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options			
Number of keys total:	2	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Luggage cover:	
Radio multimedia:		Front parking sensors:	
Type of headlighting:	Headlighting LED	Rear parking sensors:	
Type of GPS:	GPS big screen color	Type of Tow bar:	No Tow bar
Type of Lining:	Lining semi-artificial leather		
Type of climate control:	Autom climate control		
Head-up Display:			

Limited Technical Inspection

Degree of wear

225/50/17/98 V				
Winter tyres:	Fr.L.	Vredestein: 6,4 mm	Fr.R.	Vredestein: 6,6 mm
	Re.L.	Vredestein: 4,9 mm	Re.R.	Vredestein: 5,3 mm
Tyre profile depth FL:				6.4
Tyre profile depth FR:				6.6
Tyre profile depth RL:				4.9
Tyre profile depth RR:				5.3
Tyre size FL:				225/50 R 17 98 V
Tyre type FL:				Winter
Tyre make FL:				2480
Tyre make RL:				2480

Assistance equipment

Number of charging cables (normal):	0
Number of charging cables (rapid charge):	0

Total cost ex VAT	261,56
--------------------------	---------------

Tyre RR, Tear, Replace	171,56
-------------------------------	---------------



Door panel FR, Scratch(es), Acceptable	0,00
---	-------------



Bumper F, Scratch(es), Acceptable 0,00



Wing RR, Dent(s), Paintless dent repair 90,00



Bonnet, Chemical polution, Polish 0,00



Alloy rim FL, Scratch(es), Acceptable 0,00



Alloy rim RL, Scratch(es), Acceptable 0,00



Roof, Chemical polution, Cleaning 0,00



Bumper R, Scratch(es), Polish 0,00

