



**VOLVO XC40: ZV6584**

Vinnumber:	<b>YV1XZ72VCL2242683</b>	Versionname:	<b>D3 AWD Geartronic R-Design</b>
First Registrationdate:	<b>31/10/2019</b>	Fiscalpower:	
Expertise Mileage:	<b>62127</b>	Power Kw:	<b>110</b>
Bodytype:		Body colour:	<b>Light Grey</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>1526</b>
Fueltype:	<b>Diesel</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

**Options**

Number of keys total:	<b>2</b>	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Sun Roof electric:	
Radio multimedia:		Panoramic roof:	
Type of headlighting:	<b>Headlighting LED</b>	Luggage cover:	
Type of GPS:	<b>GPS big screen color</b>	Front parking sensors:	
Type of Lining:	<b>Lining semi-artificial leather</b>	Rear parking sensors:	
Type of climate control:	<b>Autom climate control</b>	Type of Tow bar:	<b>No Tow bar</b>

**Limited Technical Inspection**

**Degree of wear**

<b>235/55/18/104 V</b>			
Winter tyres:	Fr.L. <b>Michelin: 4 mm</b>	Fr.R. <b>Michelin: 4 mm</b>	
	Re.L. <b>Michelin: 4 mm</b>	Re.R. <b>Michelin: 4 mm</b>	
Tyre profile depth FL:			<b>4.0</b>
Tyre profile depth FR:			<b>4.0</b>
Tyre profile depth RL:			<b>4.0</b>
Tyre profile depth RR:			<b>4.0</b>
Tyre size FL:			<b>235/55 R 18 104 V</b>
Tyre type FL:			<b>Winter</b>
Tyre make FL:			<b>261</b>
Tyre make RL:			<b>261</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

Total cost ex VAT 1476,74

Bumper F, Scratch(es), Acceptable 0,00



Interior, Dirty, Cleaning

165,00



Bonnet, Chemical polution, Repair and paint (complete)

459,47



Bumper trim R, Dent(s) and scratch(es), Smart repair

110,00



Door panel RR, Scratch(es), Replace

171,56



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

192,50



Alloy rim RR polished, Scratch(es), Repair and paint (complete)

192,50



Rear light L, Scratch(es), Acceptable

0,00



Reflector, Crack, Replace

45,88



Outside rear-view mirror housing L, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Spot repair

139,83



Armrest, Worn, Acceptable

0,00

