



**BMW 1 HATCH: 1VTD100**

|                                    |                          |                        |                     |
|------------------------------------|--------------------------|------------------------|---------------------|
| Vinnumber:                         | <b>WBA1V710X07D17384</b> | Versionname:           | <b>116d (85 kW)</b> |
| First Registrationdate:            | <b>21/02/2019</b>        | Fiscalpower:           |                     |
| Expertise Mileage:                 | <b>83132</b>             | Power Kw:              | <b>85</b>           |
| Bodytype:                          |                          | Body colour            | <b>Grey</b>         |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Type of rims (mounted) | <b>Aluminium</b>    |
| Transmission:                      |                          | Parking lot            | <b>2806</b>         |
| Fueltype:                          | <b>Diesel</b>            |                        |                     |
| Type of rims (mounted)             | <b>Aluminium</b>         |                        |                     |
| Certificate of Conformity          | <b>Yes</b>               |                        |                     |
| Category                           | <b>Passenger Car</b>     |                        |                     |
| Registration Certificate Car (BE)  | <b>Yes</b>               |                        |                     |
| Registration Certificate Home (BE) | <b>No</b>                |                        |                     |

**Options**

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Number of keys total           | <b>2</b>                     | Front parking sensors |                   |
| Cruise Control                 |                              | Rear parking sensors  |                   |
| Steering wheel multifunctional |                              | Type of Tow bar       | <b>No Tow bar</b> |
| Radio multimedia               |                              |                       |                   |
| Type of headlighting           | <b>Headlighting LED</b>      |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining fabrics</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |

**Limited Technical Inspection**

**Degree of wear**

|                       |       |                  |       |                  |
|-----------------------|-------|------------------|-------|------------------|
| 205/55/16/94 H        |       |                  |       |                  |
| Winter tyres:         | Fr.L. | Vredestein: 4 mm | Fr.R. | Vredestein: 4 mm |
|                       | Re.L. | Vredestein: 4 mm | Re.R. | Vredestein: 4 mm |
|                       |       |                  |       |                  |
| Tyre profile depth FL |       |                  |       | 4.               |
| Tyre profile depth FR |       |                  |       | 4.               |
| Tyre profile depth RL |       |                  |       | 4.               |
| Tyre profile depth RR |       |                  |       | 4.               |
| Tyre size FL          |       |                  |       | 205/55 R 16 94 H |
| Tyre type FL          |       |                  |       | Winter           |
| Tyre make FL          |       |                  |       | 248              |
| Tyre make RL          |       |                  |       | 248              |

**Assistance equipment**

|                                          |            |
|------------------------------------------|------------|
| Repair kit                               | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |
| Number of charging cables (rapid charge) | <b>0</b>   |

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>464,21</b> |
|-------------------|---------------|

|                                  |             |
|----------------------------------|-------------|
| Wing RR, Scratch(es), Acceptable | <b>0,00</b> |
|----------------------------------|-------------|



|                                     |             |
|-------------------------------------|-------------|
| Roof, Chemical polution, Acceptable | <b>0,00</b> |
|-------------------------------------|-------------|



Internal boot lining L, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Door FR, Scratch(es), Acceptable

0,00



Tailgate / Boot, Scratch(es), Repair and paint (complete)

398,21



Boot cover, Missing, Replace

66,00

