



BMW X1: 1WCU042

Vinnumber:	WBAJH51080EK97172	Versionname:	
First Registrationdate:	26/04/2019	Fiscalpower:	
Expertise Mileage:	119558	Power Kw:	110
Bodytype:		Body colour:	Orange
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	4331
Fueltype:	Diesel		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Type of headlighting:	Headlighting LED	Rear parking sensors	
Type of GPS:	GPS big screen color	Type of Tow bar	Tow bar removable
Type of Lining:	Lining artificial leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

	225/50/18/92 H			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/50 R 18 92 H
Tyre type FL				Winter
Tyre make FL				261
Tyre make RL				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	527,60
Bumper moulding R, Scratch(es), Acceptable	0,00



Bumper moulding R, Scratch(es), Spot repair	139,83
---	--------



Seat cover FL, Damaged, Acceptable

0,00



Bumper moulding F, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), Repair and paint (complete)

279,57



Outside rear-view mirror housing L, Scratch(es), Acceptable

0,00



Door FL, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Door RL, Scratch(es), Acceptable

0,00



Bumper trim R, Scratch(es), Acceptable

0,00



Alloy rim RL polished, Scratch(es), Acceptable

0,00



Wing trim RL, Scratch(es), Replace

108,20

