



RENAULT MEGANE GRANDTOUR: 1 SBD277

Vinnumber:	VF1RFB00257322329	Versionname:	Energy dCi 110 Bose Edition
First Registrationdate:	30/03/2017	Fiscalpower:	
Expertise Mileage:	100289	Power Kw:	81
Bodytype:		Body colour	Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	4312
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		
Head-up Display			

Limited Technical Inspection

Degree of wear

205/50/17/93 H				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Fulda: 4 mm	Re.R.	Fulda: 4 mm
Tyre profile depth FL				4.
Tyre profile depth FR				4.
Tyre profile depth RL				4.
Tyre profile depth RR				4.
Tyre size FL				205/50 R 17 93
Tyre type FL				Winte
Tyre make FL				26
Tyre make RL				248

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1246,86
Rear window, Scratch(es), Replace	475,00




Bodywork, Not original part, Remove lettering	0,00
No pictures to display	
Grille, Scratch(es), Acceptable	0,00



Roof, Chemical polution, Polish

0,00



Door FL, Scratch(es), Spot repair

197,83



Bonnet, Chemical polution, Polish

0,00



Alloy rim FR, Scratch(es), Repair and paint (complete)

125,40



Bumper R, Scratch(es), Spot repair

197,83



Alloy rim RR, Scratch(es), Repair and paint (complete)

125,40



Alloy rim FL, Scratch(es), Repair and paint (complete)

125,40

