



**OPEL VIVARO: 1VSU694**

|                                   |                          |                        |                                          |
|-----------------------------------|--------------------------|------------------------|------------------------------------------|
| Vinnumber:                        | <b>W0VJ7H609KV633081</b> | Versionname:           | <b>1.6 CDTI 89kW S/S L1H1 2.7T Combi</b> |
| First Registrationdate:           | <b>19/02/2019</b>        | Fiscalpower:           |                                          |
| Expertise Mileage:                | <b>77273</b>             | Power Kw:              | <b>89</b>                                |
| Bodytype:                         |                          | Body colour            | <b>White</b>                             |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Type of rims (mounted) | <b>Steel</b>                             |
| Transmission:                     |                          | Parking lot            | <b>2507</b>                              |
| Fueltype:                         | <b>Diesel</b>            |                        |                                          |
| Maintenance                       | <b>NOT OK</b>            |                        |                                          |
| Type of rims (mounted)            | <b>Steel</b>             |                        |                                          |
| Certificate of Conformity         | <b>Yes</b>               |                        |                                          |
| Category                          | <b>VS</b>                |                        |                                          |
| Registration Certificate Car (BE) | <b>Yes</b>               |                        |                                          |

**Options**

|                                |                               |                      |                   |
|--------------------------------|-------------------------------|----------------------|-------------------|
| Number of keys total           | <b>2</b>                      | Rear parking sensors |                   |
| Cruise Control                 |                               | Type of Tow bar      | <b>No Tow bar</b> |
| Steering wheel multifunctional |                               |                      |                   |
| Radio multimedia               |                               |                      |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>   |                      |                   |
| Type of GPS                    | <b>No GPS</b>                 |                      |                   |
| Type of Lining                 | <b>Lining fabrics</b>         |                      |                   |
| Type of climate control        | <b>Manual climate control</b> |                      |                   |
| Type of GPS storage            | <b>N.A.</b>                   |                      |                   |

**Limited Technical Inspection**

**Degree of wear**

|                       |       |                  |       |                   |
|-----------------------|-------|------------------|-------|-------------------|
| 215/65/16/104 T       |       |                  |       |                   |
| Summer tyres:         | Fr.L. | Michelin: 4,6 mm | Fr.R. | Michelin: 6,2 mm  |
|                       | Re.L. | Michelin: 8 mm   | Re.R. | Michelin: 7,8 mm  |
| Tyre profile depth FL |       |                  |       | 4.6               |
| Tyre profile depth FR |       |                  |       | 6.2               |
| Tyre profile depth RL |       |                  |       | 8.0               |
| Tyre profile depth RR |       |                  |       | 7.8               |
| Tyre size FL          |       |                  |       | 215/65 R 16 104 T |
| Tyre type FL          |       |                  |       | Summer            |
| Tyre make FL          |       |                  |       | 261               |
| Tyre make RL          |       |                  |       | 261               |

**Assistance equipment**

|                                          |            |            |           |
|------------------------------------------|------------|------------|-----------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>No</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |           |
| Number of charging cables (rapid charge) | <b>0</b>   |            |           |

|                   |                |
|-------------------|----------------|
| Total cost ex VAT | <b>4856,98</b> |
|-------------------|----------------|

|                              |             |
|------------------------------|-------------|
| Wing FR, Dent(s), Acceptable | <b>0,00</b> |
|------------------------------|-------------|



|                                  |              |
|----------------------------------|--------------|
| Wheel cover RR, Missing, Replace | <b>29,70</b> |
|----------------------------------|--------------|



Roof, Dent(s) and scratch(es), Repair and paint (complete)

476,68



Air vent R, Broken, Replace

185,88



Bodywork, Not original part, Remove lettering

0,00



Bumper trim R, Dent(s) and scratch(es), Replace

200,00



Wheel cover RL, Missing, Replace

29,70



Bonnet, Dent(s) and scratch(es), Repair and paint (complete)

287,17



Dashboard, Scratch(es), Replace

735,50



Seat cover FL, Worn, Replace

382,39



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)

307,39





Door FR, Scratch(es), Paint

0,00



Seat cover R, Tear, Replace

382,60



Door trim FR, Missing, Replace

118,10



Door RR, Dent(s) and scratch(es), Repair and paint (complete)

315,16



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)

305,11



Service, Maintenance, Check

0,00



Compressor, Missing, Replace

208,42



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)

477,86



Door trim RR, Scratch(es), Smart repair

110,00



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)

305,11

